
PLAT OF SURVEY

LOT 19 AND THE EAST 1/2 OF THAT PART OF THE VACATED ALLEY LYING WEST OF AND ADJACENT TO AND BETWEEN THE EXTENDED NORTH AND SOUTH LINES OF SAID LOT, ALL IN BLOCK 11, IN THE SECOND ADDITION TO THE PLAT OF THE INTERNAL LAND COMPANY, CITY OF OSHKOSH, WINNEBAGO COUNTY, WISCONSIN.



- CHISELED "X" FOUND
- 3/4" REBAR FOUND 0
- 1-1/4" O.D. IRON PIPE FOUND ⊡
- △ 3/8" ROD FOUND IN CONCRETE WALK
- FENCE LINE
- RECORDED AS ·()

SURVEYOR'S CERTIFICATE

I hereby certify that I have surveyed the property as shown, according to official records and that the plat above drawn is an accurate and correct representation of said survey.

mor h

Martenson & Eisele, Inc.



109 West Main Street Omro, WI 54963 www.martenson-eisele.com P 920.685.6240 F 920.685.6340

Planning Environmental Surveying Engineering Architecture



PROJECT NO. 0-2040-001 FILE 2040001POS.DWG

THIS INSTRUMENT WAS DRAFTED BY: DSL