


PLAT OF SURVEY

Lot 1, Certified Survey Map No. 3925, Being Part of The Northwest Quarter of The Northeast Quarter of Section 11, Township 19 North, Range 16 East, Town of Vinland, Winnebago County, Wisconsin.

SURVEYORS CERTIFICATE:

THE PROPERTY AS SHOWN AND DESCRIBED ON THIS MAP WAS SURVEYED UNDER MY DIRECTION AND CONTROL ACCORDING TO THE WISCONSIN ADMINISTRATIVE CODE, CHAPTER A-E 7, OF MINIMUM STANDARDS FOR PROPERTY SURVEYS AND IS A CORRECT REPRESENTATION OF SAID SURVEY, TO THE BEST OF KNOWLEDGE AND BELIEF.



North Quarter Corner
Section 11, T.19N., R.16E.
Found P.K. Nail

Northeast Corner
Section 11, T.19N., R.16E.
Found Steel Survey Nail

