


Plat of Survey

Part of the Southeast $\frac{1}{4}$ of the Southwest $\frac{1}{4}$, Section 11, T20N, R17E, Village of Fox Crossing, Winnebago County, Wisconsin





LEGEND

- = Government corner
- = Set $\frac{3}{4}$ " x 18" iron rebar
Wt. = 1.502 lbs/lf
- = Found $\frac{3}{4}$ " iron rod
- ⊙ = Found 1" iron pipe
- *** = Fence line
- = Building setback line for house

NOTE:

The setback lines shown are for a house.
The rear yard and side yard setbacks for a detached garage or shed is 3 feet.



I, David Hebert, PLS, do hereby certify that this plat of survey complies with Chapter A-E7 and is correct to the best of my knowledge and belief.

Southwest Corner
Section 11-20-17

2091.64'
N89°59'52"W

NINTH STREET (66')

SCALE: 1" = 30'



South $\frac{1}{4}$ Corner
Section 11-20-17
Berntsen Monument



Hebert Associates, Inc.
Land Surveying

1110 W. Wisconsin Ave. 920-734-8373
Appleton, WI 54914 Fax: 920-734-3968

FOR:

Steve Gauerke
814 Ninth St.
Menasha, WI 54952

DATE: 2-12-21

DRAFTED BY: DH

SCALE: 1" = 30'

DRAWING NUMBER:

20095A01